



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	ES/LOM/QAR16.0002/04	Page 1 of 1																		
QAR Free Ref. No.:	LOM 22.04057	Status: Issued																		
Details of change:	Re-Assessment audit	Date of issue: 2022-06-06																		
Site(s) audited:	Delvalle Global Solutions, S.L.U. Paso El Prao, 6. 01320, Oyón. Alava Spain	Valid until: 2025-01-20 Audit date: 2022-01-20																		
Issuing ExCB:	LOM - Laboratorio Oficial J.M. Madariaga (LOM)																			
Manufacturer:	Delvalle Global Solutions, S.L.U. Paso El Prao, 6. 01320, Oyón. Alava. Spain.																			
Location of Manufacturer:	Spain																			
Product information:	Empty boxes, connection boxes, switchgear boxes, control stations, signal lamp module, switch module, operation head, circuit breaker module, electric apparatus module, electrical box accesories, controller, electrical equipment.																			
Protection concept:	Increased safety "eb", protection by enclosure "tb", intrinsic safety "i" (Ex ia/ib), flameproof enclosure "db" and encapsulation "mb".																			
Related QARs:	ES/LOM/QAR16.0002/00 ES/LOM/QAR16.0002/03 ES/LOM/QAR16.0002/01 ES/LOM/QAR16.0002/02																			
Related Certificates (manual insertion)::																				
Related Certificates (automatic linking)::																				
Related Certificates for previous versions:	<table><tr><td>IECEX CML 19.0079U issue: 0</td><td>IECEX CML 19.0080U issue: 0</td><td>IECEX CML 19.0081U issue: 0</td></tr><tr><td>IECEX CML 19.0082U issue: 0</td><td>IECEX CML 19.0083U issue: 0</td><td>IECEX CML 19.0084U issue: 0</td></tr><tr><td>IECEX CML 19.0085U issue: 0</td><td>IECEX CML 19.0086U issue: 0</td><td>IECEX CML 19.0087X issue: 0</td></tr><tr><td>IECEX CML 19.0088X issue: 0</td><td>IECEX INE 21.0034X issue: 0</td><td>IECEX LOM 16.0002U issue: 0</td></tr><tr><td>IECEX LOM 16.0002U issue: 1</td><td>IECEX LOM 16.0003U issue: 0</td><td>IECEX LOM 16.0003U issue: 1</td></tr><tr><td>IECEX LOM 16.0004U issue: 0</td><td>IECEX LOM 16.0004U issue: 1</td><td>IECEX LOM 18.0001X issue: 0</td></tr></table>		IECEX CML 19.0079U issue: 0	IECEX CML 19.0080U issue: 0	IECEX CML 19.0081U issue: 0	IECEX CML 19.0082U issue: 0	IECEX CML 19.0083U issue: 0	IECEX CML 19.0084U issue: 0	IECEX CML 19.0085U issue: 0	IECEX CML 19.0086U issue: 0	IECEX CML 19.0087X issue: 0	IECEX CML 19.0088X issue: 0	IECEX INE 21.0034X issue: 0	IECEX LOM 16.0002U issue: 0	IECEX LOM 16.0002U issue: 1	IECEX LOM 16.0003U issue: 0	IECEX LOM 16.0003U issue: 1	IECEX LOM 16.0004U issue: 0	IECEX LOM 16.0004U issue: 1	IECEX LOM 18.0001X issue: 0
IECEX CML 19.0079U issue: 0	IECEX CML 19.0080U issue: 0	IECEX CML 19.0081U issue: 0																		
IECEX CML 19.0082U issue: 0	IECEX CML 19.0083U issue: 0	IECEX CML 19.0084U issue: 0																		
IECEX CML 19.0085U issue: 0	IECEX CML 19.0086U issue: 0	IECEX CML 19.0087X issue: 0																		
IECEX CML 19.0088X issue: 0	IECEX INE 21.0034X issue: 0	IECEX LOM 16.0002U issue: 0																		
IECEX LOM 16.0002U issue: 1	IECEX LOM 16.0003U issue: 0	IECEX LOM 16.0003U issue: 1																		
IECEX LOM 16.0004U issue: 0	IECEX LOM 16.0004U issue: 1	IECEX LOM 18.0001X issue: 0																		
Comments:																				