



# IECEX Quality Assessment Report Summary

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit [www.iecex.com](http://www.iecex.com)

QAR Ref. No.:	<b>ES/LOM/QAR16.0002/02</b>	Page 1 of 1
QAR Free Ref. No.:	<b>LOM 19.04222</b>	Status: <b>Issued</b>
Details of change:	Re-Assessment audit and include types of protection flameproof enclosure "d", encapsulation "m" and intrinsic safety "i"	Date of issue: <b>2019-08-29</b> Valid until: <b>2022-02-28</b>
Site(s) audited:	Delvalle Global Solutions, S.L.U. Paso El Prao, 6. 01320, Oyón. Alava. Spain.	Audit date: <b>2019-02-28</b>
Issuing ExCB:	<b>LOM - Laboratorio Oficial J.M. Madariaga (LOM)</b>	
Manufacturer:	<b>Delvalle Global Solutions, S.L.U.</b> Paso El Prao, 6. 01320, Oyón. Alava. Spain.	
Location of Manufacturer:	<b>Spain</b>	
Product information:	Empty boxes, connection boxes and control stations.	
Protection concept:	<b>Increased safety "eb", protection by enclosure "tb", intrinsic safety "i" (Ex ia/ib), flameproof enclosure "db" and encapsulation "mb".</b>	
Related QARs:		
	<a href="#">ES/LOM/QAR16.0002/00</a>	<a href="#">ES/LOM/QAR16.0002/01</a>
Related Certificates (manual insertion)::		
Related Certificates (automatic linking)::		
IECEX CML 19.0079U issue: 0	IECEX CML 19.0080U issue: 0	IECEX CML 19.0081U issue: 0
IECEX CML 19.0082U issue: 0	IECEX CML 19.0088X issue: 0	IECEX CML 19.0084U issue: 0
IECEX CML 19.0085U issue: 0	IECEX CML 19.0086U issue: 0	IECEX CML 19.0087X issue: 0
IECEX CML 19.0083U issue: 0		
Related Certificates for previous versions:		
IECEX LOM 16.0002U issue: 0	IECEX LOM 16.0002U issue: 1	IECEX LOM 16.0003U issue: 0
IECEX LOM 16.0003U issue: 1	IECEX LOM 16.0004U issue: 0	IECEX LOM 16.0004U issue: 1
IECEX LOM 18.0001X issue: 0		
Comments:		