



IECEx Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	ES/LOM/QAR16.0002/02	Page 1 of 1
QAR Free Ref. No.:	LOM 19.04222	Status: Issued
Details of change:	Re-Assessment audit and include types of protection flameproof enclosure "d", encapsulation "m" and intrinsic safety "i"	Date of issue: 2019-08-29 Valid until: 2022-02-28
Site(s) audited:	Delvalle Global Solutions, S.L.U. Paso El Prao, 6. 01320, Oyón. Alava. Spain.	Audit date: 2019-02-28
Issuing ExCB:	LOM - Laboratorio Oficial J.M. Madariaga (LOM)	
Manufacturer:	Delvalle Global Solutions, S.L.U. Paso El Prao, 6. 01320, Oyón. Alava. Spain.	
Location of Manufacturer:	Spain	
Product information:	Empty boxes, connection boxes and control stations.	
Protection concept:	Increased safety "eb", protection by enclosure "tb", intrinsic safety "i" (Ex ia/ib), flameproof enclosure "db" and encapsulation "mb".	
Related QARs:	ES/LOM/QAR16.0002/00 ES/LOM/QAR16.0002/01	
Related Certificates (manual insertion):		
Related Certificates (automatic linking):	IECEX CML 19.0079U issue: 0 IECEX CML 19.0080U issue: 0 IECEX CML 19.0081U issue: 0 IECEX CML 19.0082U issue: 0 IECEX CML 19.0088X issue: 0 IECEX CML 19.0084U issue: 0 IECEX CML 19.0085U issue: 0 IECEX CML 19.0086U issue: 0 IECEX CML 19.0087X issue: 0 IECEX CML 19.0083U issue: 0	
Related Certificates for previous versions:	IECEX LOM 16.0002U issue: 0 IECEX LOM 16.0002U issue: 1 IECEX LOM 16.0003U issue: 0 IECEX LOM 16.0003U issue: 1 IECEX LOM 16.0004U issue: 0 IECEX LOM 16.0004U issue: 1 IECEX LOM 18.0001X issue: 0	
Comments:		